

Hyde County, SD Windrow Pulverizer

Problem Statement:

Increased size of agricultural trucks and equipment along with increased speeds are causing new maintenance challenges on gravel roads. A major reshape of the roadway and shoulder is needed every 3-5 years. The real problem develops when large amounts of dirt, gravel and chunks of sod are pulled up onto the road. These windrows cannot be quickly pulverized and mixed.

Solution:

The county built their own double drum windrow pulverizer that can be towed by a mower tractor. It has performed very well with only minor modification and repair.

Contact:

Mr. Ron Van Den Berg, Hwy Superintendent
PO Box 260
Highmore, SD 57345

