

Pennington County, SD Flexible Bridge Marker

Problem Statement:

Wide farm loads that protrude over the top of narrow bridge structures are constantly breaking off Type III object markers. Replacement costs are substantial .

Solution:

A flexible mounting for Type III bridge mounted object markers was developed using common materials. Material cost, not including use of salvaged items, is \$0.60 each.

Contact:

Jack C. Dier, Superintendent
Pennington County
3601 Highway 79 South
Rapid City, SD 57701-2204
605-394-2166

